Approved For Release 2000/05/31 : CIA-RDP89B00551R000200180024-4 25X1A S SHE SLANT CHE TWO FOUR FIVE ZULU IN 21215 25X1A ONE ZERO THREE FIVE ZULU EMAVO: CHARLIE: AT APPROX ZERO NINE THREE EIGHT ZULU OBSERVED WHAT APPEARED TO BE ONE SINGLE CUMULUS TYPE CLOUD IN THE VICINITY OF THE TURNISH DASH SYRIAN BORDER AT THREE SIX THREE SIX. THIS WAS OBSERVED FROM APPROX THREE ZERO MILES DISTANT. . IT APPEARED TO START FROM SURFACE AND WAS INTENSIFYING RAPIDLY. APPROX FIVE MINUTES LATER HOTHING REMAINED BUT ALFA COUPLE OF SMALL WISPS OF CLOUD APPROXIMATED TWO ZERO ZERO, BOILING NATURE AT TOP AND RAPID DISSIPATION LEADS US TO BELIEVE IT MAY HAVE BEEN SOME KIND OF EXPLOSION INSTEAD OF A CLOUD. DASH FIVE WILL BE MONITORED CLOSELY FOR THIS PHENOMENON. DELTA: NO SIGNIFICANT DEVIATIONS. ECHO: ALFA ONE THRU ONE ONE ALFA, SPACE ONE TWO THRU ONE FOUR ECHO. TARGETS NOVEMBER AND OSCAR WERE MISSED DUE TO FAILURE OF IDLER GEAR SHAFT IN SHUTTER. ASSUMING MISSION IS RESCHEDULED, RECORMEND TARGETS MOVEMBER AND OSCAR BE COVERED FIRST. REMARKS: HYCON NOTICE TO FIELD SUPERVISORS RECEIVED BY DETACH MYCON SECTION REPORTS THAT HOTEL SIERRA SEVEN THREE TWO DESIGN IMPHOVEMENT MODS RELEASED FOR PRODUCTION TWO FOUR MAY FIVE SEVEN, INCLUDES IDLER SHAFT MOD, NEW DESIGN OF WHICH ELIMINATES IDLER SHAFT AND BUSHING. SHAFT AND BUSHING TO BE COMBINED INTO ONE SOLID PIECE, PRESSED INTO CASTING. TWO ROLLER BEARINGS WILL BE PRESSED INTO GEAR. ACCORDING TO HYCON, THIS SHOULD ELIMINATE ENTIRELY ANY FURTHER BREAKING OF IDLER GEAR SHAFT CONNENT: AS MOS AWARE, INSTANT CASE WAS FOURTH CHEER SHAFT EMEAKAGE ENCOUNTERED BY DETACH. FOR FORTHCOMING STAGING OPERATION 25X1A UTILIZED THAT UOULD APPEAR DESIRABLE IF DETACH HAVE AVAILABLE LATEST HOTEL SIERRA SEVEN THREE TWO SMUTTERS WHICH INCORPORATE LATEST MODS REPEAT LATEST MODS HENTLONED IN ABOVE HYCON REPORT. IN ORDER INSURE OPTIMUM RELIABILITY, IT APPEARS THAT IF NEWEST SHUTTERS NOT AVAILABLE 25X1A FOR STAGING, WOULD BE MORE PRUDENT UTILIZE VIEW RELIABILITY FACTOR. 25X1A CUMULUS TURKISH DASH SYRIAH APPROX UISPS 25X1A PHENOMENON THRU THRU IDLER HYCON DETACH HYCON HAY MOD HGS LATEST MODS NOT

5 er 3 by

ATOP SECRET

Cafee and the second		
UPCMARKUNAL	อักษณะเป็นได้เป็นได้ เลื่อง	
25X1A OPIM CITE FOUR EIGHT FOUR ZERO	N S & S & S & S S S S S S S S S S S S S	
25X1A TWO ZERO ONE EIGHT O	NE ZERO ZULU 3	
1382	<b>J W J</b>	1
ALFA ONE THREE EIGHT TUO	IN 21153	- - -
ERAVO TWO ONE JUN FIVE SEVEN		<b>3</b> 1
CHARLIE	25X1A	
DELTA	25X1A	₩
ECHO ZERO SIX ZERO ZERO ZULU	25X1A	
FOXTROT ONE ZERO THREE ZERO ZULU	25X1A	
COLF POINT ECHO ZERO SEVEN TWO FIVE ZULU		
HOTEL NONE		
REMARKS:		
1. INITIAL SUCCESS ONE THREE EIGHT ZEI  MALFUNCTION CEAR AND SHUTTER OF EQUIPMENT COMPLETED.		25X1A 25X1A
2. REQUEST NOT BE DISMAYED TO PRIMARY PURPOSE OF FLIGHT WAS CHECK OF LARGE LOAD, SOMETHING NEVER USED HERE.  SATISFACTORY.	) TRANSPORT	25X1A 25X1A
(A) SHUTTER MALFUNCTION OCCURRED. USUUTTER (SAVING OUR THREE GOOD ONES FOR O		
AND LEARNED OF ANOTHER POSSIBLE MALFUNCTION		
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE ONE THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING MENCE NO OBLIQUE DRIVE. NEW DRIVE MOTORS	ON WITH AGE.  A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA	
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE ONE THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING	ON WITH AGE.  A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA	
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE ONE THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING MENCE NO OBLIQUE DRIVE. NEW DRIVE MOTORS LESS JOLTING ACTION. HOWEVER, HEED MORE IN	A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA MOTORS FOR OTHER  O FAILURES CAN BE DIRE  SPARES	25X1A CCTLY 25X1A
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE ONE THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING NEMCE NO OBLIQUE DRIVE. NEW DRIVE MOTORS LESS JOLTING ACTION. HOWEVER, HEED MORE IN THREE UNITS.  (C) IN SUMMARY, ONE THREE EIGHT ZERA ATTRIBUTED TO INSUFFICIENT STOCK CRITICAL TO PERMIT OPTIMUM OPERATION	A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA MOTORS FOR OTHER  O FAILURES CAN BE DIRE  SPARES	25X1A CCTLY 25X1A
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE ONE THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING NEMCE NO OBLIQUE DRIVE. NEW DRIVE MOTORS LESS JOLTING ACTION. HOWEVER, NEED MORE IN THREE UNITS.  (C) IN SUMMARY, ONE THREE EIGHT ZER ATTRIBUTED TO INSUFFICIENT STOCK CRITICAL TO PERMIT OPTIMUM OPERATION HOW WITHOUT ADVERSELY AFFECTING PERFORMAN SPARES ARE ENROUTE OR ON ORDER, OR BOTH.	A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA MOTORS FOR OTHER  O FAILURES CAN BE DIRE  SPARES	25X1A CCTLY 25X1A
(B) OBLIQUE DRIVE, OLD SYSTEM IS ALFA ONCE BEFORE SHEAR PIN BROKE (SEE OME THREE THIS TIME SET SCREWS JARRED LOOSE CAUSING MENCE NO OBLIQUE DRIVE. NEW DRIVE MOTORS LESS JOLTING ACTION. HOWEVER, MEED MORE IN THREE UNITS.  (C) IN SUMMARY, ONE THREE EIGHT ZER ATTRIBUTED TO INSUFFICIENT STOCK CRITICAL TO PERMIT OPTIMUM OPERATION MOW WITHOUT ADVERSELY AFFECTING PERFORMAN SPARES ARE ENROUTE OR ON ORDER, OR BOTH.	A ROUGH JOLTING MOVEME E SEVEN SIX REPORTS).  GEAR SLIP ON SHAFT,  SMOOTH DRIVE TO ALFA MOTORS FOR OTHER  O FAILURES CAN BE DIRE  SPARES  CE OPERATION FIRST TIME	25X1A 25X1A 25X1A

Approved For Release 2000/05/31 : CIA RD 89E00551R000200180024-4

25X1A

IN 21211

FOUR EIGHT FOUR SEVEN

25X1A

TWO ONE SLANT ONE ZERO FIVE

FIVE ZULU

25X1A

ERAVO TWO ONE SLANT ONE ZERO THREE FIVE ZULU JUN FIVE SEVEN

CHARLIE ESTIMATE OF MISSION SUCCESS: APPROX NINETY PERCENT, COVERAGE. DELTA LIGHT WENT OUT JUST PRIOR TO LAST TWO TARGETS.

WEATHER: AS BRIEFED

MAVIGATION: EXCELLENT

COMMUNICATIONS: POOR

DELTA REMARKS: NONE

CFH: APPROX NONE